		REVISED Cable	
FREA NO. H 7.6  CRITICALITY 2/18		SHUTTLE CCTV CRITICAL ITEMS LIST	Cable ONG NO. 2293290-501,502 1\$\$UED 10-14-86 \$MEET 1 DF 5
FAILURE MODE AND FAILURE EFFECT ON END ITEM		RATIONALE FOR ACCEPTANCE	
oss of +28V power (RMS) pen/Short to GNO	1) No video from wrist camera stack 2) No video from elbow camera stack 3) No elbow PTU control Worst Case: No PTU control of elbow camera which prevents arm stowage.	DESIGN FEATURES  The M7 RYS/RMS cable is a 20-inch long assembly, terminated on each end with a 37-pin connector (I wires are shielded #24 Twinax twisted-pair wires commands from the RVS to the RMS wrist or elbow to the RVS.  The cable design is taken from the successfully cable-connector assembly in which the wire terminal flexture at the joint between the wire and the connectoration is moved away from the conductor of the length of the conductors encapsulated in a palso protects the assembly from dirt and entrapped in space.  The cable and its components neet the applicable specifications. These requirements include:  • General/Hechanical/Electrical Features • Design and Construction • Materials • Terminal Solderability • Environmental • Qualification • Marking and Sarialization • Traceability and Documentation	Pl, KJ66E14M35SN16). The video and sylling the W7 cable provides power and camera stack and returns video signals flown Apollo program. The design is a mations are protected from excessive panector terminal. The load panection and distributed axially along otted-taper profile. This technique and moisture which could cause problems
1			
	d	I .	

REVISED 5-7-87

FMEA NO. N 7.6 CRITICALITY 2/18		SHUTTLE COTV CRITICAL ETEMS LIST	URIT CADIE OMG ND. 2293290-501,502 ISSUED TO-14-86 SHEET 2 DF 5
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ETEM	RATIONALE FOR ACCEPTANCE	
7		QUALIFICATION TEST  Qualified by 1.) similarity to previous successful qualification tests of CCTV LRUs.  ACCEPTANCE TEST  The cable acceptance test consists of an obuncted connection is present and intact. Results are resolved to the camera proper and intact. Results are resolved to the CAPAI) panel switch, through the RCU, the to the Camera/PTU command decoder are proper. The bility to produce video, the YSU's ability to redisplay video. A similar test verifies the MOM of the Pro-Launch on Orbiter Test/in-flight Test  1. Power CCTV System. 2. Select a monitor via the PHS panel, as dest source. 3. Sand "Camera Power On" command from PHS panel. Select "External Sync" on monitor. If vides stable raster), then this indicates that the from the RCU and that the camera is product for Send Pan, Tilt, Focus, Zoom, ALC, and Gamma monitor or direct observation) verify propersum the RCU and that the camera is product for Select Downlink as destination and camera used to downlink. 9. Send "Camera Power Off" command via PHS panel Repeat Steps 3 through 9 except issue command proves that the CCTV aquipment is operation.	r check to assure that each wire ecorded on data sheets.  are operable and that the commands from rough the sync lines to the Camera/PTU, he tests also verify the camera's dute video and the monitor's ability to command path.  ination and the camera under test as el.  eo on monitor is synchronized (i.e., a camera is receiving composite sync ng synchronized video. commands and visually (either via the roperation, ander test as source.  el.  nds via the MDM command path. This

FHEA NO. N 7.6		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT Cable  DING MO. 2293290-501,502  ISSUED 10-14-86  SHEET 3 OF 5
FAILURE MODE AND FAILURE EFFECT		RATIONALE FOR ACCEPTANCE	
.oss of +28V power (RMS)  Dpen/Short to GND	ON END ITEM  1) No video from wrist camera stack 2) No video from albow camera stack 3) No elbow PTU control  Norst Case:  No PTU control of elbow camera which prevents arm stowage.	Procurement Control - Mire, connectors, solder, etc. are procured from approved vending suppliers which meet the requirements set forth in the CCTV contract and Quality Plan Mork Statement (MS-2593176).  Incoming Inspection & Storage - Incoming Quality inspections are made on all receives materials and parts. Results are recorded by lot and retained in file by drawing an control numbers for future reference and traceability. Accepted items are delivered Material Controlled Stores and retained under specified conditions until cable fabrication is required. Non-conforming naterials are held for Material Review Board (MRB) disposition. (PAI-307, PAI IQC-53).  Assembly & Test - Prior to the start of assembly, all items are verified to be correby stock room personnel as the items are accumulated to form a kit. The Items are verified again by the operator who assembles the kit by checking against the as-built-parts-list (ABPL).  Specific instructions are given in assembly drawing notes and applicable documents called out in the Fabrication Procedure and Record (FPR-2293290). These are 2280800 Process Standard crimping flight connector contacts, 2280801 - Process Standard in-1 splicing of standard interconnecting where using Raychem solder sleaves, 2280876. Proting material and test procedure (TP-AT-2293290). Quality and DCAS Inspections are perforant the completion of key operations.  Preparation for Shipment - When fabrication and test is complete, the cable assembly packaged according to 2280746, Process Standard for Packaging and Mandling Guideline All related documentation including assembly drawings, Parts List, ABPL, lest Data, is gathered and held in a documentation folder assigned specifically to each cable assembly. This folder is retained for reference.	
	ı	Ī	

REVISED 5-7-87

		~~ =		
FMEA NO. <u>U 7.6</u> CRETICALETY <u>2/1R</u>		SHUTTLE COTY CRITICAL ITEMS LIST	UNIT Cable DWG NO. 2293290-501,502 ISSUED TO-14-86 SHEET 4 OF 5	
FATLURE HODE AND CAUSE	FAYLINE EFFECT ON END ITEM	RATIONALE FOR ACC	EPTANCE	
FATLURE HODE AND CAUSE  Loss of +28V power (RMS)  Open/Short to GNO	FAILURE EFFECT ON END ITEM  1) No video from wrist camera stack 2) No video from elbow camera stack 3) No elbow PTU control  Norst Case: No PTU control of elbow camera which prevents arm stowage.	FAILURE MISTORY There have been no reported failures during RCA		

REVISED 5-7-87

FMEA NO. N 7.6		SHUTFLE CCTY CRITICAL ITEMS LIST	ONTT Cable ONE NO. 2293290-501,502 ISSUED 10-14-86 SHEET 5 OF 5	
FATLURE HODE AND FATLURE EFFECT CAUSE ON END IYEN		RATIONALE FOR ACCEPTANCE		
Loss of +28V power (RMS) Open/Short to GND	1) No video from wrist camera stack 2) No video from elbow camera stack 3) No elbow PTU control  Warst Case: No PTU control of elbow camera which prevents arm stowage.	Loss of ability to position the Elbow camera. Possition the Elbow camera physically interferes with a payload, payload bay door cannot be closed. Loss of crew and CREM ACTIONS  Bow Perform EVA to reposition the elbow camera, use RMS: jettison the RMS.  CREW TRAINING  Crew should be trained in contingency EVA and RMS opening the camera for any flight where the interfere with each other (for any pan or tilt angle not change the camera position until the interfering	I. If RMS camnot be stowed the port and vehicle.  RMS motion to reposition the camera, on sometions procedures.  The payload and the elbow camera can ngle). If the camera must be flown do	